

---

# NOTICE TO MARINERS

---

**No. H. 28/2026**

## U P P E R H U M B E R

### SHOAL WATER

**MARINERS ARE WARNED** that a survey carried out on the 24th of February 2026 shows the following:

- 1) A least depth of 2.4 metres **ABOVE** Chart Datum exists North of the ships course 335 metres downstream of the Lower Whitton Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) A least depth of 0.3 metres below Chart Datum exists North of the ships course from 180 metres to 480 metres downstream of the No. 31 Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 3) A least depth of 0.6 metres below Chart Datum exists close North of the ships course 480 metres downstream of the No. 33 Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 4) A least depth of 0.4 metres **ABOVE** Chart Datum exists South of the ships course 225 metres downstream of the No. 33A Light Float.

Deeper water exists on the ships course in this vicinity.

- 5) A least depth of 0.4 metres **ABOVE** Chart Datum exists North of the ships course 345 metres upstream of the No. 32C Light Buoy.

Deeper water exists on and to the South of the ships course in this vicinity.

**MARINERS ARE ADVISED** that 0 metres at Chart Datum should be used for passage planning purposes and that Notice to Mariners No. H. 18/2026 is hereby cancelled.

**CAPT. A. FIRMAN**  
**HARBOUR MASTER, HUMBER**

24<sup>th</sup> February 2026

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.  
[www.humber.com](http://www.humber.com)